

PURETI Clear is a non-toxic, environmentally friendly, water and titania based, photocatalytic mineral film former that contains highly photoactive anatase Titanium Dioxide suspended in water. PURETI Clear air dries to form durable, ultra-thin and invisible film that oxidizes organic micro particles when irradiated by UV light. PURETI Clear was specially developed for glass windows, solar panels, ceramics, LED screens, polycarbonate and other glossy surfaces. PURETI Clear creates a sustainable, self-cleaning surface that continuously breaks down grime, odors, VOCs and organic film buildup. PURETI Clear is ready to use and should not be diluted.

#### Features and Benefits:

- Formulated to create a photocatalytic surface which continuously oxidizes organic micro particles at the molecular level.
- When light charged, it creates a hydrophilic surface that causes water to sheet away.
- Reduces exterior cleaning maintenance costs by up to 50%, water, energy, chemicals, and labor expanded in cleaning.
- Treated surfaces help eliminate odors, reduce VOCs and improve IAQ.

#### LIGHT REQUIREMENTS:

PURETi Clear coated surfaces need the UV irradiance of 0.1 mW/cm2 to trigger the selfcleaning properties and 0.001 mW/cm2 to trigger odor abatement.

## **SURFACE PREPARATION:**

- Surface to be treated with PURETi Clear must be thoroughly clean.
- Clean glass surfaces with a professional grade ammonia based cleaner.
- If surfaces are stained, please consult your PURETi specialist for recommended product alternatives.

# **APPLICATION:**

- Temperature should be in the range of 40-90°F and relative humidity should be at least 30%
- Stir/shake the material thoroughly before each use.
- Surface must be completely dry before application.
- Apply one (1) light coat in a cross-hatch manner using a electrostatic spray (ESS) gun or a High Volume Low Pressure (HVLP) spray gun. We recommend spraying a ¼" overlap. Application pressure should be maintained between 30-40 psi. and distance from the substrate should be 3-4 ft (ESS) or 6-8 inches (HVLP)
- PURETi Clear dries to the touch within minutes depending on environmental conditions. Do not apply PURETi Clear if rain is expected within 48 hours from the time of intended application.
- Do not clean treated surface with PURETi Clear for at least 14 days after application.
- Clean up equipment with deionized water and rinse thoroughly.



### **COVERAGE:**

PURETi Clear covers approximately 4,000 square feet per gallon on glass surfaces.

#### **PACKAGING:**

PURETi Clear is available in 5 and 55 gal containers.

## PRODUCT DESCRIPTION:

Color and Odor: Translucent pale yellow with bland smell

VOC: No Data

Density: 8.33 lbs/gal

Weight Solids: 0.50 +/-0.05%

Volume Solids: <0.50%

pH: 6.5-8.5

Flash Point: Not Applicable

Chemical Stability Stable

Hazardous By-Products: None Known
Hazardous Polymerization: Will not occur

Use of Protective Equipment: None required under normal use. If conditions exist that

result in prolonged direct exposure, rubber gloves, half face

respirators and safety glasses are recommended

# **Storage Requirements:**

- Material is frost sensitive.
- Recommended storage temperature: 40°F 90°F (5°C 32°C).
- Shelf life: 2 year stored in original, unopened containers at temperature not to exceed 95°C

### Waste Disposal:

- Use completely or dispose of in accordance with local, state, and federal regulations.
- Refer to MSDS for further information.

This information presented herein is our interpretation of certain test results and field experience to date. This information is not to be taken as warranty or representation for which we assume legal responsibility. Consult your Coatings Specialist Group<sup>--</sup> representative to obtain the most recent Product Data Sheet.